

KERALA MEDICAL SERVICES CORPORATION LTD

(A Government Of Kerala Undertaking) Thycaud.P.O., Thiruvananthapuram-14. Tele Fax No. 0471-2945647 0471-2945646, 0471-2945600 E-mail id : <u>eptenders.kmscl@kerala.gov.in</u> CIN : U24233KL2007SGC021616 GSTIN: 32AADCK4029M1ZK

EP Division

No: KMSCL/EP/662/2024

www.kmscl.kerala.gov.in

Dated: 28.09.2024

NOTICE

Sub:- Tender No.T522/ 2024 - Cancellation Notice - Sterilizer Various Types - reg.

Ref:- 1. Tender Inviting Notice published dated 04.10.2023

2. Technical bid opening held on 27.10.2023 @ 11.00 A M

3. Eligible list published on 28.11.2024

4. Demonstration/ document evaluation of Sterilizer Various Types conducted on 31.05.2024

I. The reports of technical document evaluation/ demonstration of Laryngoscope Various Types as per reference no. 4th cited above were submitted by the technical committee appointed for the purpose. The details of the tenderers participoated in the technical evaluation are as follows:

1. KMSCL/EP/T522/115/2024: Sterilizer Various Types (Steriliser Small)

A. M/s Universal Agencies.

Rejected Model: GIVA 1265/GEETA INDUSTRIES Reason for rejection

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality constructions with joints of the lid failing even during the demonstration. The power chord supplied is not satisfactory for prolonged use as it is prone to loose contact and failure. The thermostat provided is not set at 100 0 and can vary, resulting in improper sterilization or boiling dry.

B. M/s Kerala Surgical Equipment Co

Rejected Model: PE-01/Paras Enterprises

Reasonf or rejection:

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality
		constructions with joints of the lid failing even
		during the demonstration. The power chord
		supplied is not satisfactory for prolonged use as it
		is prone to loose contact and failure. The
		thermostat provided is not set at 100 0 and can
		is prone to loose contact and failure.

vary, resulting in improper sterilization or boiling dry.

C. M/s Genist Tec hnocracy Vt Ltd

Rejected Model: GTA-001/Genist Technocracy

Reason for rejection: Sample not produced

2. KMSCL/EP/T522/115/2024: Sterilizer Various Types (Steriliser Medium)

A. M/s Universal Agencies.

Rejected Model: GIVA 1786/GEETA INDUSTRIES Reason for rejection:

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality constructions with joints of the lid failing even during the demonstration. The power chord supplied is not satisfactory for prolonged use as it is prone to loose contact and failure. The thermostat provided is not set at 100 0 and can vary, resulting in improper sterilization or boiling dry.

B. M/s Kerala Surgical Equipment Co

Rejected Model: PE-02/Paras Enterprises Reason for rejection

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality constructions with joints of the lid failing even during the demonstration. The power chord supplied is not satisfactory for prolonged use as it is prone to loose contact and failure. The thermostat provided is not set at 100 0 and can vary, resulting in improper sterilization or boiling dry.

C. M/s Genist Technocracy Vt Ltd

Rejected Model: GTA-001/Genist Technocracy Reason for rejection: Sample not produced

3. KMSCL/EP/T522/115/2024: Sterilizer Various Types (Steriliser large)

A. M/s Universal Agencies.Rejected Model: GIVA 2086/GEETA INDUSTRIESReason for rejection:

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality constructions with joints of the lid failing even during the demonstration. The power chord supplied is not satisfactory for prolonged use as it is prone to loose contact and failure. The thermostat provided is not set at 100 0 and can vary, resulting in improper sterilization or boiling dry.

B. M/s Kerala Surgical Equipment Co

Rejected Model: PE-03/Paras Enterprises

Clause No	Technical Specification	Deviations Noted
	Comments	The equipment demonstrated had poor quality constructions with joints of the lid failing even during the demonstration. The power chord supplied is not satisfactory for prolonged use as it is prone to loose contact and failure. The thermostat provided is not set at 100 0 and can vary, resulting in improper sterilization or boiling dry.

C. M/s Genist Technocracy Vt Ltd

Rejected Model: Sample not produced

III. Due to technical reason the tender for KMSCL/EP/T522/115/2024: Sterilizer Various Types is cancelled.

Dr. Shibulal A General Manager